# Observations from at IRS2007 terminals

V_pow disconnected, Vs connected to motor, other 3 phases active.

LIN(blue) and HIN(yellow)

# LIN(blue) and HIN(yellow) same as previous

# LIN(blue) and HIN(yellow) motor shaft rotated manually (position changed)

LIN(blue) and HIN(yellow) same as before

HIN(blue) and HO(yellow)

HIN(blue) and HO(yellow) same as previous

LIN(blue) and LO(yellow)

LIN(blue) and LO(yellow)